



## Luxmeter Typ LX1330B



### Product characteristics

- Battery indicator
- 4 selectable measuring ranges
- Large LCD display
- Hold function
- Self-calibration

### Delivery scope

- Calibration certificate
- 1 x battery (type 23 A)
- Storage box
- Operating instructions

### Technical data

Measuring range:	0 - 200,000 Lux
Resolution Display:	1 Lux
Measuring accuracy:	<20,000 Lux + / - 3 % > 20,000 Lux + / - 5
Photo sensor dimensions:	100 x 60 x 28 mm
Dimensions measuring device:	149 x 71 x 41 mm
Power supply:	1 x 9 Volt block battery
Weight:	280g (with battery)
Ambient temperature:	-10 °C to 60 °C
Humidity:	0-80%

**NOTE: NOT** suitable for measurements of the white light component in UV light!

\*\*technical changes reserved!\*\*